

Range 11
Town 1
Section 19
Staunton Tow.
369.95A. in Sec.
Plat No. 27
SEC. 20
0.103 Ac.
SUR. VOL. 19-PG. 67
SEE PLAT 28 FOR OWNERSHIP
CENTERLINE PLAT REC. 24-83
Vol. 8 Pg 60
ENG'R REC ROADS
ELDEAN COVERED BRIDGE
ELDEAN RD. RELOCATED IN THE ENG'R. REC. OF ROAD SURVEYS VOL. 8, PG. 60 RD REC. 9-38 REC. BK. 25-12
DONALD E. & SALLY K. APPLE D.B. Trustees OR 217-46
34.1027 AC.
TOTAL AC. 51.1305
SUR. VOL. 33 PG. 150
33.114 AC. IN SEC. 19 (8.621 AC. IN SEC. 20)
TOTAL 41.735 AC.
CLARK LEE WAGNER D.B. 590-480
SUR. VOL. 7, Pg. 1
1150.66
49.24
1120.4
3249.84
1965.80 TOTAL
1318.40
13.30.3
1326.9 to corner
SEE PLAT 28-A
PIQUA-TROY RD. 60' R/W
SMDA NUMBER K30-STD27
SEC. 9 CONCORD
MIAMI RIVER
DB 724-474
James R Hartzell Jr & Jacqueline S. Hartzell - Trustees
DB 789261
DB 701-96 715-390
125.000
10.100
114.900
SUR. VOL. 34 PG. 42
10.100
Wade H. & Susan M. Westfall
DB 594-357
632.56
Concord Twp.
SUR. VOL. 4-189 D.B. 160-262 179-402
11.404
D.B. 593-831
SUR. VOL. 34 PG. 181
Ernest L. & Billie S. Shaefer
Sur BK. #9, Pg. #30
Jacob J. Rindler
Jacob J. & Mary Elizabeth Rindler Trustees D.B. 730-400
Lawrence D. & Linda S. Cavanaugh
Benjamin A. & Lindsey A. Goodin OR 65-426
Jerry L. & Linda G. Miller D.B. 641-631
Sur. Vol. 5 - Pg 187
Philip M. & Glenna L. Osting D.B. 543-776
F. W. & Susan F. Huntsman D.B. 560-935
SPRING CREEK
SEC. 16 CONCORD
ANNEXED TO TROY REC. 25-79
117.2782 AC.
LND. 39-101
SEC. 13
SEE PLAT 21 FOR OWNERSHIP
SCALE - 1" = 330'
W.H. & S.M. WESTFALL D.B. 716-702
SEC. 24
2453.86'
Lnd. 45-142
Surveys
Cen Pt. of Sec - Vol. 4 Pg. 189 Vol. 8 Pg. 40 - N Cen. Pt. NE
E. Pt. SE - Vol. 5 Pg. 187 Vol. 8 Pg. 110 - E Cen. Pt. NE
NW. Pt. NE - Vol. 7 Pg. 1 Vol. 9 Pg. 30 - E Cen Pt SE
NE Cor. NE - Vol. 7 Pg. 75 Vol. 8 Pg. 60 - New Eldean Rd. & Bridge
NE Cor. SE & SE Cor NE - Vol. 8 Pg. 6 Vol. Pg.
Lnd. 45-142 SE Pt. SE Qtr.
REVISED 3-8-2016 D. VENTURA